



# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8

999 18<sup>TH</sup> STREET- SUITE 300 DENVER, CO 80202-2466 Phone 800-227-8917 http://www.epa.gov/region08

Ref: 8EPR-SR

July 24, 2006

Alternative Housing Group LLC 1854 W 33<sup>rd</sup> Ave Denver, CO 80211

**RE: 4638 York St** 

Dear Owner.

As part of the VB/1-70 Superfund Site investigation, we recently took soil samples at your property to find out if there is too much lead or arsenic in your yard. The results show that your property does not require a cleanup. The levels of both lead and arsenic are below our cleanup levels. The soil sampling results for your property are as follows:

ADDRESS: «Address»

EPA Cleanup Levels

Lead

193 parts per million (ppm)

above 400 ppm

Arsenic

13 ppm

above 70 ppm

This means that your property is not considered by EPA to be part of the VB/I-70 Superfund Site. EPA does not believe that further measures are necessary. You and your family are not at significant risk from arsenic through ordinary contact with soil in your yard while playing, working, gardening, etc. Please note that there may be small areas in your yard, particularly near your house, that may have higher levels of lead due to peeling, external lead-based paint. EPA encourages all owners of older properties to take reasonable precautions regarding lead-based paint.

For further information, please feel free to contact EPA Community Involvement Coordinators Jennifer Chergo at (303) 312-6601 or Patricia Courtney at (303) 312-6631.

Sincerely,

Victor Ketellapper

Remedial Project Manager

The Environmental Protection Agency, Region 8



#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Victor Ketellapper
Phone 800-227-8917
http://www.epa.gov/region08

#### **CONSENT FOR ACCESS TO PROPERTY**

Name: Alternative Housing Group, LLC (or current property owner)

Location of Property: 4638 York St

Property ID: 6074

I consent to officers, employees, and authorized representatives of the United States Environmental Protection Agency (EPA) entering and having continued access to the above referenced property for the purpose of taking samples of soil on the Site.

I realize that these actions are undertaken pursuant to EPA's response and enforcement responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA or Superfund), 42 U.S.C. § 9601 et seq.

Printed Name

10 Howard Hutsbu Munger 303 3245087

Phone Number

Signatura

Date

#### Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

-- Client Sample ID: VB-4638-YO-01

Client Project ID: 213001.01 Date Collected: 1/26/06 Date Received: 2/7/06

Method: SW6010

Date Prepared: 2/17/06

Date Analyzed: 2/17/06

Lab Work Order: 06-0774 Lab Sample ID: 06-0774-30

Sample Matrix: Soil

METALS Pr

Prep Method: SW3050

Dilution Factor: 1
Lab Fraction ID: 06-0774-30A

Method Blank: MB-9270 Lab Fraction ID: 06-0774-30A

 Analytes
 CAS Number
 Result
 LQL
 Units

 Arsenic
 7440-38-2
 24
 5.0
 mg/Kg

 Lead
 7439-92-1
 270
 7.3
 mg/Kg

021706PM

Lab File ID:

Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

11 - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Approved

Definitions: NA - Not Applicable

1.Ql. - Lower Quantitation Limit

Sur - Surrogate

Print Date: 2/20/06

## Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

lient Sample 1D: VB-4638-YO-02

Client Project ID: 213001.01 Date Collected: 1/26/06

Date Received:

2/7/06

Lab Work Order: 06-0774

Lab Sample 1D: 06-0774-31

Sample Matrix:

Soil

M	ET	'Δ	I.	S
172	C I	л	ı	•

Method: SW6010 Prep Method: SW3050

Date Prepared: 2/17/06 Lab File ID: 021706PM Dilution Factor: 1

Date Analyzed: 2/17/06 Method Blank: MB-9270 Lab Fraction ID: 06-0774-31A **CAS Number** Result LQL Analytes Units 8.9 Arsenic 7440-38-2 5.0 mg/Kg 7439-92-1 190 7.3 mg/Kg Lead

Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

11 - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

mb.

Approved

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 2/20/06

### Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-4638-YO-03

Client Project 1D: 213001.01 Date Collected: 1/26/06 Date Received: 2/7/06 **Lab Work Order:** 06-0774 **Lab Sample ID:** 06-0774-32

Sample Matrix: Soil

METALS

Method: SW6010 Prep Method: SW3050

Date Prepared: 2/17/06 Lab File ID: 021706PM Dilution Factor: 1

Date Analyzed: 2/17/06 Method Blank: MB-9270 Lab Fraction ID: 06-0774-32A

Analyzes CAS Number Result LOL Units

Analytes CAS Number Result LQL Units

Arsenic 7440-38-2 U 5.0 mg/Kg Lead 7439-92-1 120 7.3 mg/Kg

Analyst

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

F - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

I - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Print Date: 2/20/06

Definitions: NA - Not Applicable

Surr - Sprrogate

LQL - Lower Quantitation Limit

4	1638 YORK Street Apprx		
0 4	Δ	Section Grid Points 5'	
a	Canasa A	02 72 11	
	A	3 97 15 191/30 4.36	
12   98   2	Trub Con 1	VB 4636 VD - 01 02 VB 4636 VD - 02 A	
*	Α Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ	12F5 P	
	Morre #2 II	1225 A 1225 A 12 30 VB-4074-005-8BC	
	* D A		
*	* 4		
		607	4

-